

### **General Data**

Change Nr,Title Date of issue	20007911,Add UKCA marking 28.06.2021		
		Category of change	<ul> <li>Materials</li> <li>Method</li> <li>Manufacturing place</li> <li>Machine</li> <li>Form</li> <li>Fit</li> <li>Function</li> </ul>

# Affected products

See appendix

### **Description of change**

UKCA marking introduced on affected products.

### **Reason for change**

Compliance regulation introduced in UK.

#### Impact for the customer

None.

# Identification

UKCA marking is visible on product label, product box label and data sheet where applicable.



Figure 1: UKCA marking







Figure 3: Example product label after change



### **Estimated Schedule**

Applied on all new orders of affected products by end October 2021 the latest.

### **Customer enquiries**

You may address any technical enquiries regarding this PCN by sending an E-Mail to pcn@schaffner.com. Please refer to the "Change number" on page 1 for faster response.

### **Quality assurance measures**

Application of ISO9001:2015 and exceeding Schaffner standards for outstanding quality in all involved design centers and manufacturing locations.

Date of announcement

28.06.2021

Schaffner Group

Nordstrasse 11e CH-4542 Luterbach www.schaffner.com PCN

# Appendix

List of affected products

FN251	FN1393	FN3271H	FN3530	FN9233	FN9255	FN9292
FN256	FN1393	FN3280H	FN3531	FN9233B	FN9255B	FN9292B
FN258	FN2010	FN3280HL	FN3532	FN9233E	FN9255EB	FN92920
FN256	FN2010	FN3280HL	FN353Z	FN9233EB	FN9255EMB	FN9299B
FN281	FN2020	FN3280HQ1	FN3540	FN9233ER	FN9255ESB	FS3530
FN282	FN2050		FN3540		FN9255ESB	RWK212
FN283	FN2060	FN3280HQ2 FN3287	FN3541	FN9233ES FN9233ES1	FN9255MB	RWK3044
FN283	FN2070	FN3288	FN3545	FN9233ES1	FN9255S	RWK305
FN285	FN2071	FN3288HV	FN3840		FN9255SB	RWK305
FN285	FN2080	FN3288HVIT	FN385B	FN9233ES1R FN9233ESB	FN925555	C13-Locking-Outlet-1.5mm
FN286B	FN2090	FN3288IT		FN9233ESB	FN9260A	5
			FN388B			C19-Locking-Outlet-1.5mm
FN286E	FN2092	FN3310	FN389B	FN9233EU	FN9260A1	SYNC300A SYNC300X
FN332	FN2200	FN3310HV	FN393E	FN9233EUB	FN9260B	
FN332Z	FN2210	FN3311	FN394E	FN9233R	FN9260S	CABINET 380-480VAC IP54 3W
FN343	FN2211	FN3311HV	FN5040	FN9233S	FN9260SA	CABINET 380-415VAC IP54 4W
FN350	FN2220	FN3311HVIT	FN5040HV	FN9233S1	FN9260SB	C13-4 Tier-Locking Outlet
FN351	FN2221	FN3311IT	FN5045	FN9233S1B	FN9262	C13-6 Tier-Locking Outlet
FN351H	FN2230	FN3359	FN5060	FN9233S1F2	FN9262A	
FN352Z	FN2231	FN3359B	FN5060HV	FN9233S1R	FN9262B	
FN354	FN2320Y	FN3359HV	FN610B	FN9233SB	FN9262S	
FN355	FN2410	FN3359HVB	FN6840	FN9233SF2	FN9262SA	
FN356	FN2412 FN2415	FN3359HVPV FN3359PV	FN9222	FN9233SR	FN9262SB	
FN370			FN9222A FN9222AR	FN9233U FN9233UB	FN9263	
FN372 FN372B	FN2450B	FN3410 FN3410HV	FN9222AR FN9222B	FN92330B	FN9263S	
	FN2560		-		FN9263S1	
FN375	FN2580 FN3021	FN3411	FN9222E	FN9244	FN9264	
FN378 FN379	FN3021 FN3025HL	FN3412 FN3413	FN9222EB FN9222ER	FN9244B FN9244E	FN9264B FN9264S	
FN379 FN379B		FN3413 FN3416	FN9222ER FN9222ES		FN9264S FN9264SB	
	FN3025HP			FN9244EA		
FN380	FN3026HL	FN3416LV	FN9222ES1	FN9244EB	FN9266	
FN382	FN3100	FN3418	FN9222ES1B	FN9244ER	FN9266A	
FN382B FN385	FN3120H FN3256H	FN3418LV FN3420	FN9222ES1R	FN9244ES	FN9266B FN9266S	
FN388	FN3258	FN3420	FN9222ESB FN9222ESR	FN9244ES1 FN9244ES1B	FN9266SA	
FN389	FN3258A	FN3430	FN9222ESR	FN9244ES1B	FN9266SB	
FN309 FN393	FN3258B	FN3440	FN9222EU FN9222EUB	FN9244ESTR	FN92003B	
FN393	FN3258H	FN3441	FN9222E0B	FN9244ESB	FN9274B	
FN409	FN3258P	FN3442	FN9222R	FN9244ESK	FN9274MB	
FN409 FN420	FN3258Q	FN3450	FN9222RA	FN9244E0	FN9280	
FN420	FN3258T	FN3451	FN9222S	FN9244S	FN9280B	
FN610	FN3258T1	FN3451	FN9222S1	FN9244S1	FN9280E	
FN612	FN3258T2	FN3453	FN9222S1B	FN9244S1B	FN9280EB	
FN660	FN3268	FN3470	FN9222S1B	FN9244S1B	FN9282-	
FN660B	FN3268I	FN3470	FN9222SB	FN9244STR FN9244SB	FN9282-	
FN670	FN3268Q3	FN3471 FN3472	FN9222SB	FN9244SB	FN9289	
FN670	FN3266Q3	FN3472	FN92220K	FN92445K	FN9289 FN9289B	
FN685 FN686	FN3270HN FN3270HQ1	FN3480 FN3481	FN9222UB FN9222UZ	FN9246 FN9246A	FN9289E FN9289EB	
FN000 FN700Z	FN3270HQ1 FN3270HQ2	FN3481 FN3482	FN9226	FN9246A	FN9209ED	
FN1392	FN3270HQ2	FN3482	FN9226B	FN9246EB	FN9290	
1111032		I NUTUU	TNJZZOD	TNJZHUED	11192300	

The listed materials are being modified. Related materials that are not explicitly listed on this PCN are not being modified nor discontinued as per the PCN. If any questions, please ask according "Customer enquiries"